

## COMMON FEATURES

Easy to read seven segments display.  
Stabilization time: 3 seconds.  
ON/OFF. Automatic Zero adjustment  
External automatic calibration.

Tare range by subtraction up to maximum capacity.  
Piece counting function. Overload indicator.  
Operating temperature: from 5 to 35 °C.  
Voltage: 220 V  $\pm$ 10 V / 50 Hz

MODELS	Part No.	Maximum weight capacity g	Precision $\pm$ g	Height / Width / Depth (exterior) cm	$\emptyset$ plate cm	Weight Kg
LABORCOM 110-L	5830025	110	0.01	7 17.5 24	12.5	1.6
LABORCOM 210-L	5830026	210	0.02	7 17.5 24	12.5	1.6
LABORCOM 600-L	5830031	600	0.1	7 17.5 24	12.5	1.6
LABORCOM 1100-L	5830032	1100	0.1	7 17.5 24	12.5	1.6
LABORCOM 2100-L	5830033	2000	0.1	7 17.5 24	12.5	1.6
LABORCOM 11000-L	5830027	11000	1	7 17.5 24 16.5 x 16.5	1.8	

